



High Beam Module Issues

These include objects blocking the camera, misaligned sensors, a dirty windshield, hardware failures, or software glitches. We hope you find the [Auto High Beam Assist Not Working](#) ...

Hi, I have a 2024 P4X and have been having issues with this feature since the day I received the truck.

I had the FWM reprogrammed and everything works again except I have no high beam and the main beam turns off. The blue high beam icon flashes on the dashboard when you move the ...

When high beams remain stuck, first inspect the headlight switch for wear or internal damage. Check the multifunction switch on the steering column, as its contacts may be faulty.

2021+ Ford F150 - LED headlight High Beam Failure - So just posting this for information, 21 F150 Powerboost XLT 302A noticed that high beam on the drivers side LED headlight stopped working.

Diagnose and fix automatic high beam problems with our [step-by-step guide](#) covering sensor failure, fuse issues, and DIY troubleshooting.

Hi all, I recently bought an VW Golf 7 from 2015. The headlights (xenon) are working fine, but when I turn on the high beam, the high beam is not working...

High beams not working? The problem with these headlights is probably the result of one of nine common causes.

I had some initial issues with mine where it seemed to be a little late in switching back to low beam with on-coming traffic. After a few miles it stabilized and seems to react based on speed, ...

Discover the [7 most common reasons](#) your high beams won't turn on and how to fix each issue, from blown fuses to faulty switch contacts.



High Beam Module Issues

Web: <https://safireschools.co.za>

